

- L----- 3x0.75/1.5 Cu wire
- K----- 15A/ 220V/ 110V Switch
- Fu----- 5A / 10A fuse
- D----- 80W/220v/110V Ac motor
- W----- 20V-220V linearity booster
- V----- 220V/110V Ac voltage meter
- R----- 950w/220v/110V heating piece

